

United States Patent and Trademark Office

UNITED STATES DEPARTMENT OF COMMERCE United States Patent and Trademark Office Address: COMMISSIONER FOR PATENTS P.O. Box 1450 Alexandria, Virginia 22313-1450 www.uspto.gov

APPLICATION NO.	· FILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO.	
10/759,117	01/20/2004	Hirohisa Fujita	14-024	14-024 6658	
23400	7590 09/19/2005		EXAM	EXAMINER	
POSZ LAW GROUP, PLC 12040 SOUTH LAKES DRIVE			TRAN, D.	TRAN, DALENA	
SUITE 101			ART UNIT	PAPER NUMBER	
RESTON, V	A 20191		3661	3661	

DATE MAILED: 09/19/2005

Please find below and/or attached an Office communication concerning this application or proceeding.

ir)	<i>C</i> ₂				
	Application No.	Applicant(s)				
Office Action Symmony	10/759,117	FUJITA ET AL.				
Office Action Summary	Examiner	Art Unit				
	Dalena Tran	3661	Idea a			
The MAILING DATE of this communication app Period for Reply	ears on the cover sheet with the c	orrespondence ad	iaress			
A SHORTENED STATUTORY PERIOD FOR REPLY WHICHEVER IS LONGER, FROM THE MAILING DA - Extensions of time may be available under the provisions of 37 CFR 1.13 after SIX (6) MONTHS from the mailing date of this communication. - If NO period for reply is specified above, the maximum statutory period w - Failure to reply within the set or extended period for reply will, by statute, Any reply received by the Office later than three months after the mailing earned patent term adjustment. See 37 CFR 1.704(b).	ATE OF THIS COMMUNICATION 6(a). In no event, however, may a reply be tim ill apply and will expire SIX (6) MONTHS from a cause the application to become ABANDONE	l. ely filed the mailing date of this c O (35 U.S.C. § 133).				
Status						
1) Responsive to communication(s) filed on 30 Ju	ne 2005.					
3) Since this application is in condition for allowar	3) Since this application is in condition for allowance except for formal matters, prosecution as to the merits is					
closed in accordance with the practice under E	x parte Quayle, 1935 C.D. 11, 45	3 O.G. 213.	!			
Disposition of Claims						
4)⊠ Claim(s) <u>2-7</u> is/are pending in the application.						
4a) Of the above claim(s) is/are withdrawn from consideration.						
5)⊠ Claim(s) <u>4-7</u> is/are allowed.						
	6)⊠ Claim(s) <u>2 and 3</u> is/are rejected.					
7) Claim(s) is/are objected to.	r alaction requirement					
8) Claim(s) are subject to restriction and/or	election requirement.					
Application Papers						
9) The specification is objected to by the Examine						
10) The drawing(s) filed on is/are: a) accepted or b) objected to by the Examiner.						
Applicant may not request that any objection to the drawing(s) be held in abeyance. See 37 CFR 1.85(a). Replacement drawing sheet(s) including the correction is required if the drawing(s) is objected to. See 37 CFR 1.121(d).						
11) The oath or declaration is objected to by the Ex	• • • • • • • • • • • • • • • • • • • •					
Priority under 35 U.S.C. § 119						
12) Acknowledgment is made of a claim for foreign priority under 35 U.S.C. § 119(a)-(d) or (f). a) All b) Some * c) None of:						
1. Certified copies of the priority documents have been received.						
2. Certified copies of the priority documents have been received in Application No.						
3. Copies of the certified copies of the priority documents have been received in this National Stage						
application from the International Bureau (PCT Rule 17.2(a)). * See the attached detailed Office action for a list of the certified copies not received.						
See the attached detailed Office action for a list	of the certified copies not receive	u.				
Address and a						
Attachment(s) 1) Notice of References Cited (PTO-892)	4) Interview Summary	(PTO-413)				
2) Notice of Draftsperson's Patent Drawing Review (PTO-948)	Paper No(s)/Mail Da	ate	0.450)			
3) Information Disclosure Statement(s) (PTO-1449 or PTO/SB/08) Paper No(s)/Mail Date	5) Notice of Informal P 6) Other:	atent Application (PT	O-152)			

0

Application/Control Number: 10/759,117

Art Unit: 3661

DETAILED ACTION

Notice to Applicant(s)

1. This office action is responsive to the amendment filed on 6/30/05. As per request, claim 1 has been cancelled, claims 2-4, and 6 have been amended. Thus, claims 2-7 are pending.

Claim Rejections - 35 USC § 103

- 2. The following is a quotation of 35 U.S.C. 103(a) which forms the basis for all obviousness rejections set forth in this Office action:
 - (a) A patent may not be obtained though the invention is not identically disclosed or described as set forth in section 102 of this title, if the differences between the subject matter sought to be patented and the prior art are such that the subject matter as a whole would have been obvious at the time the invention was made to a person having ordinary skill in the art to which said subject matter pertains. Patentability shall not be negatived by the manner in which the invention was made.
- 4. Claim 2, is rejected under 35 U.S.C.103(a) as being unpatentable over Matsuda et al. (4,939,725) in view of Yoshida et al. (6,534,883), and Hogg et al. (5,408,412).

As per claim 2, Matsuda et al. disclose a failure diagnosis method of communication network for a vehicle that is constructed by an electronic control device and a plurality of electronic control instruments provided with a failure diagnosis portion being connected to a main line of a multiplex communication line comprising the steps of: storing different diagnosis trouble codes respectively, at a failure diagnosis portion of the electronic control device, when the electronic control instrument is malfunctioning, or when an abnormality including disconnection or short circuit has occurred in a communication line from the main line of the multiplex communication line to a branch line that is connected to the electronic control instrument (see at least columns 1-2, lines 40-19; column 3, lines 18-64; columns 4-5, lines 35-27; and columns 6-7, lines 31-45). Matsuda et al. do not disclose measuring a resistance value. However, Yoshida et al.

Application/Control Number: 10/759,117

Art Unit: 3661

٦,

disclose measuring a resistance value of the main line resistance in the multiplex communication line, and identifying an abnormality portion in the communication network by a combination of the measured resistance value of the main line and the diagnosis trouble code that is stored in the failure diagnosis portion (see at least columns 7-8, lines 27-56). Matsuda et al. also do not disclose the measuring the diagnosis trouble code is performed after the measuring main line resistance. However, Hogg et al. disclose the measuring the diagnosis trouble code is performed after the measuring main line resistance of the multiplex communication line, and the abnormality portion is identified by combining the diagnosis trouble code and the measured resistance value (see columns 11-12, lines 36-68). It would have been obvious to one of ordinary skill in the art at the time the invention was made to modify the teach of Matsuda et al. by combining measuring a resistance value of the main line resistance in the multiplex communication line, and the measuring the diagnosis trouble code is performed after the measuring main line resistance for providing an accurate data to perform failure diagnosis in vehicle communication network.

5. Claim 3, is rejected under 35 U.S.C.103(a) as being unpatentable over Matsuda et al. (4,939,725) in view of Yoshida et al. (6,534,883).

As per claim 2, Matsuda et al. disclose a failure diagnosis method of communication network for a vehicle that is constructed by an electronic control device and a plurality of electronic control instruments provided with a failure diagnosis portion being connected to a main line of a multiplex communication line comprising the steps of: storing different diagnosis trouble codes respectively, at a failure diagnosis portion of the electronic control device, when the electronic control instrument is malfunctioning, or

Art Unit: 3661

when an abnormality including disconnection or short circuit has occurred in a communication line from the main line of the multiplex communication line to a branch line that is connected to the electronic control instrument (see at least columns 1-2, lines 40-19; column 3, lines 18-64; columns 4-5, lines 35-27; and columns 6-7, lines 31-45). Matsuda et al. do not disclose measuring a resistance value. However, Yoshida et al. disclose measuring a resistance value of the main line resistance in the multiplex communication line, and identifying an abnormality portion in the communication network by a combination of the measured resistance value of the main line and the diagnosis trouble code that is stored in the failure diagnosis portion (see at least columns 7-8, lines 27-56). Matsuda et al. also do not disclose the measuring the main line resistance is performed after the diagnosis trouble code. However, Yoshida et al. disclose the measuring the main line resistance of the multiplex communication line is performed after the measuring the diagnosis trouble code that is stored in the failure diagnosis portion is detected, and the abnormality portion is identified by combining the diagnosis trouble code and the measured resistance value (see columns 8-10, lines 57-23; columns 11-12, lines 53-10; and columns 16-18, lines 24-21). It would have been obvious to one of ordinary skill in the art at the time the invention was made to modify the teach of Matsuda et al. by combining measuring a resistance value of the main line resistance in the multiplex communication line, the measuring the main line resistance of the multiplex communication line is performed after the measuring the diagnosis trouble code that is stored in the failure diagnosis portion is detected for identifying the main line resistance value corresponding to abnormality signal position.

6. Claims 4-7 are allowable.

Application/Control Number: 10/759,117

Art Unit: 3661

• • •

Remarks

Page 5

7. Applicant's amendment filed on 6/30/05 has been fully considered. Upon reviewing the claims and updated search, the allowance of claims 2-3 in the last office

action is withdrawn, and the new ground of rejection has been set forth as above.

8. Any inquiry concerning this communication or earlier communications from the

examiner should be directed to Dalena Tran whose telephone number is 571-272-6968.

The examiner can normally be reached on M-F 6:30 AM-4:00 PM), off every other

Friday.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's

supervisor, Thomas Black can be reached on 571-272-6956. The fax phone number for

the organization where this application or proceeding is assigned is 571-273-8300.

Information regarding the status of an application may be obtained from the

Patent Application Information Retrieval (PAIR) system. Status information for

published applications may be obtained from either Private PAIR or Public PAIR. Status

information for unpublished applications is available through Private PAIR only. For

more information about the PAIR system, see http://pair-direct.uspto.gov. Should you

have questions on access to the Private PAIR system, contact the Electronic Business

Center (EBC) at 866-217-9197 (toll-free).

Patent Examiner
Dalena Tran

Dalenton

September 14, 2005